

10

Page of

W.O Number 2047245

Item	COMMENTS
------	----------

North Avenue	1:00	115°
Int Washington	3:00	121°
Lutherville	4:00	110°

Rolando Chumacero

1992

Page 4 of 4

W.O Number 2045548

Item	COMMENTS
------	----------

10:00 Am	837 SWIRIT	101°
12:00 PM	N. AVE	114°

Robert A. Churnick

76

of

W.O Number 2086813 / "

Item	COMMENTS
------	----------

Ralph C. Shuman

74

Rachel A. Churner

74

of

W.O Number 2047778

Item	COMMENTS
------	----------

NO

Yes _____ NO ✓

NO

Supervisory Certification

Isabel A. Chennel

(Please Print)

LYNTHICUM

To

Стомиле

Item	COMMENTS
------	----------

NO NEW DEFECTS NOTED IN AREA

9:00 AM LINDEN RD. CROSSING 84°

10:00 Am LINDTICHM

Were Switch In the area of Inspected Yes ✓ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes _____ NO ☒

SPECIAL INSPECTION Yes_____ NO ☒

Reason for special inspection ? _____

Stu Luce

Supervisory Certification _____

Robert A. Churchill

1990

(Please Print)

Inspected From

Item	COMMENTS
------	----------

NO NEW DEFECTS NOTED IN AREA

Yes _____ NO ☒

Reason for special inspection ? _____

Supervisory Certification

St. Louis

Rabbi a Chennel

7

Page 1 of 1

W.O Number 2045593 /

To Lufherville

[illegible]

Yes _____ NO X

SPECIAL INSPECTION Yes_____ NO X

Reason for special inspection ? _____

Supervisory Certification _____

CS J. Chandru
Deputy Father

Rabeta Chennett

TRACK INSPECTION REPORTING FORM

Name Chandler Date 8/20/15 Page 1 of 1
 (Please Print)
 Watchman Chandler W.O Number 20455191
 Inspected From Cold Spring To Camden

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

NO new defects noted in
 AREA

Riding Inspection

Were Switch in the area of Inspected Yes visually only NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position?
 Yes NO ☒

SPECIAL INSPECTION Yes NO ☒

Reason for special Inspection ? _____

Track Inspector Signature

Chandler

Supervisory Certification _____

Robert A. Chandler

TRACK INSPECTION REPORTING FORM

Name Chandler Date 8/20/15 Page 1 of 1
 (Please Print)
 Watchman _____ W.O Number 2045519
 Inspected From PENN To _____

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

No New Defects
 noted In AREA
 Riding Inspection

Were Switch In the area of Inspected Yes visually NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
 Yes NO ☒

SPECIAL INSPECTION Yes _____ NO ☒

Reason for special Inspection ? _____

Track Inspector Signature

C. Chandler

Supervisory Certification _____

Rabindra Kumar

14

Page of

(Please Print)

To

W.O Number 2045545,

Item	COMMENTS
------	----------

[illegible]

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes _____ NO ✓

Reason for special inspection ? _____

Track Inspector Signature 

Rachel A. Churns

17

(Please Print)

[illegible]

CD/CDL

Figure 1

Page / of /

W.O Number 2041473 /

To Commonwealth

[illegible]

Supervisory Certification

7. 10. 1991

Page of

W.O Number 2054194

Item	COMMENTS
------	----------

No New Defects Noted in Area

8-26-15